







2		1				
LOC	SHEET	REVISIONS				
A1	-	REVISION				
		REVISION				
		REVISION				
		REVISION				
		REVISION				
PROJECT NO. ESA INC.	P	LTR	DATE	CHK	APPR	
		B	CARRIER REWORKED	2/28/82	FE	CE
		C	LEVER REWORKED	1/28/82	FE	CE
		C	THIO ELECTRONICS SYMBOL (CHANGED PEN E-10-00383)	2/27/82	NP	CE
		D	CHAMBER DELETED SEE PEN E-15-003942	2/28/82	NP	CE



D		C		B		A		C		B		A	
D	1-1718484-4	D	1	PRT-0P20	YELLOW	LEVER							
			2	PRT-ASA-0P30	YELLOW GREEN	CARRIER CODE B							
			3	PRT-ASA-0P30	YELLOW GREEN	TR-1890 HASTINGSON C							
1-1718484-3	D	1	PRT-0P20	YELLOW	LEVER								
		2	PRT-0P20	YELLOW	CARRIER CODE C								
		3	PRT-0P20	YELLOW	TR-1890 HASTINGSON C								
B	1-1718484-2	D	1	PRT-0P20	YELLOW	LEVER							
			2	PRT-0P20	DUSTY GRAY	CARRIER CODE B							
			3	PRT-0P20	DUSTY GRAY	TR-1890 HASTINGSON B							
A	1-1718484-1	D	1	PRT-0P20	YELLOW	LEVER							
			2	PRT-ASA-0P30	BLACK	CARRIER CODE A							
			3	PRT-ASA-0P30	BLACK	TR-1890 HASTINGSON A							
CODE		REV.		QTY		MAT.		COLOR		DESCRIPTION		REV. ITEM	
REV. ORDER-MIL. TO BRANCH-REV.		REV.		QTY		MAT.		COLOR		DESCRIPTION		REV. ITEM	

NOTES
Bemerkungen

- | | |
|---|---|
| 1 | TYPE ELECTRONICS (Type logo and TE NUMBER
Type Electronics (TE) logo and TE Number) |
| 2 | FITS TO THE RECEPTACLE INSERT AMP MCP 1.5K
7 POSITION: 1778A09-1
Terminal to Receptaculum AMP MCP 1.5K
7 pos.: 1778A09-1 |
| 3 | FITS TO THE RECEPTACLE INSERT AMP MCP 2.8
7 POSITION: 1778A08-1
Terminal to Receptaculum AMP MCP 2.8
7 pos.: 1778A08-1 |
| 4 | PRODUCTION DATE
Produktionsdatum |
| 5 | MATERIAL IDENTIFICATION ACC. TO VDA 260
Materialkennzeichnung nach VDA 260 |
| 6 | WARRANTY TO . . . PERMITTED
Warranty and Usage Info . . . |


 CODING MARKING
Kodierungskennzeichnung

- | | |
|----|--|
| 8 | BULK PACKAGING IN CORRUGATED BOX
Schüttgut in Versandkarton |
| 9 | FITS TO TE COUNTERPART 1,5/2,8 MM TAB HOUSING, 18+TPDS
1789491
Passt zu TE Gegenstück 1,5/2,8 mm Flachsteckergel., 18-Teil.
1789491 |
| 10 | MAJFUNCTION CAUSED BY LACQUER IS NOT
COVERED BY TE IN WARRANTY
Funktionsbeeinträchtigung durch Lackieren liegt nicht
im Einfluss und Gewährleistungsumfang von TE |

CODING A AS SHOWN
Kodierung A wie gezeigt

DELIVERY CONDITIONS
Lieferzustand:

LEVER IN LOCKED POSITION
Hebel in Verriegelungsstellung

[illegible]