

SYMBOL DEFINITION		SYMBOLS
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.	TOTAL NO OF INSPECTIONS REQUIRED	50
	LAST NO. USED	16

MISSING SYMBOLS: 12-13

| REVISION HISTORY | | |